U.S. Patent No. 7,280,144 B2

Attorney Docket No.: 15162/06070

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.:

7,280,144 B2

Issued:

October 9, 2007

To:

Tomokazu KAKUMOTO and Masayuki KUSUDA

For:

SOLID-STATE IMAGE SENSING DEVICE

WITH REDUCED LEAK CURRENT

U.S. Serial No.:

10/630,984

Filed:

July 30, 2003

Certificates of Correction Branch -

Commissioner for Patents

00000005 181260 07/24/2008 CKHLOK

7280144

10630984

P.O. Box 1450

01 FC:1811

Alexandria, VA 22313-1450

02 FC:1808 139.99 DA

Dear Sir:

REQUEST FOR CERTIFICATE OF **CORRECTION UNDER 37 C.F.R. 1.323**

It is respectfully requested that a Certificate of Correction be issued for U.S. Patent No. 7,280,144 B2, issued October 9, 2007, for the purpose of correcting errors which occurred in the printing of the patent due to Applicants' error.

Please note that when the Part B - Fee(s) Transmittal was prepared and filed on September 6, 2007, the name of the Assignee, City and Country were omitted. The corporation box was checked.

In accordance with the requirements of MPEP 1481.01, the Assignment for this patent was submitted for recordation as set forth in 37 CFR 3.11 before issuance of the patent. This Assignment to Minolta Co., Ltd. was recorded at Reel/Frame No. 014356/0073.

Attached is Form PTO-1050 (PTO/SB/44) which is suitable for printing.

U.S. Patent No. 7,280,144 B2 Attorney Docket No.: 15162/06070

The printing errors in U.S. Patent No. 7,280,144 B2 are set forth below:

Cover page, (76) Inventors: "Tomokazu Kakumoto, c/o Minolta Co., Ltd., Osaka Kokusai Bldg., 3-13, 2-Chome, Azuchi-Machi, Chou-Ku, Osaka-Shi, Osaka 541-8556 (JP); Masayuki Kusuda, c/o Minolta Co., Ltd., Osaka Kokusai Bldg., 3-13, 2-Chome, Azuchi-Machi, Chou-Ku, Osaka-Shi, Osaka 541-8556 (JP)" should read "Tomokazu Kakumoto, Nagaokakyo-shi (JP);". "Masayuki Kusuda, Nishinomiya-shi (JP)".

Please add the following on the Cover Page: -- (73) Assignee:. Minolta Co., Ltd., Osaka (JP) --.

The foregoing mistake was due to Applicants' error. Accordingly, pursuant to 37 C.F.R §1.20(a), please charge \$100.00 to cover the fee for issuance of a Certificate of Correction to Sidley Austin LLP's Deposit Account No. 18-1260. If any additional fees are due please charge them to Deposit Account No. 18-1260. Please credit any overpayment to Deposit Account No. 18-1260.

Please issue a Certificate of Correction and transmit the Certificate to the attorney whose signature and address appear below.

Respectfully submitted,

By:/Douglas A. Sorensen/ Reg. No. 31,570
Douglas A. Sorensen
Registration No. 31,570
Attorney for Patentees

TTN/AR/IIb SIDLEY AUSTIN LLP 717 North Harwood Suite 3400 Dallas, Texas 75201 (214) 981-3482 Direct (214) 981-3300 Main (214) 981-3400 Facsimile February 6, 2008